![Digital Watchdog logo — DW Digital Watchdog, Everything's Digital](image)

Cube **Recovery** Disc

```
Please select boot device:

P#: WDC WD30EURS-63SPKY0
Windows Boot Manager (P#: WDC WD30EURS-63SPKY0)
UEFI: ********
********
Enter Setup

        ↑ and ↓ to move selection
        ENTER to select boot device
        ESC to boot using defaults
```

1. Press [F7] to select a boot device when boot post splash is displayed

2. Insert Cube Recovery disc

3. Select "Optical Drive" that has Cube Recovery disc is loaded and press enter

4. Wait while Acronis True Image is loading

5. Once *Acronis True Image* is ready, click **My Disks** under where it says *Recover*

5. Click **Browse for backup** from *Data Recovery and backup manage-ment*

6. From browse window, select CD Drive first and select
"DW_CUBE_****_full~" then click **OK**

ⓘ **** represents Spectrum build number.

7. Right click loaded image then click **Recover**

8. Click **Next**

9. Click all checkboxes of each partitions from item selection window

⚠ Do NOT select all partitions by clicking "Select All" checkbox.

It may cause Acronis to block a user from selecting a target disk.

10. Continue to click **Next** until *Summary* window appears

⚠ You do not have to change the size of each partitions as long as target disk is
   3TB .

11. Click **Proceed**

11. Wait until recovery is done.

ℹ System will automatically reboot once recovery is complete